

Illinois Department of Public Health

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  <b>IL6003792</b>	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____  B. WING _____	(X3) DATE SURVEY COMPLETED  <b>09/13/2018</b>
--	--	---	---

NAME OF PROVIDER OR SUPPLIER  <b>PIPER CITY REHAB &amp; LIVING CENTER</b>	STREET ADDRESS, CITY, STATE, ZIP CODE <b>600 MAPLE STREET PIPER CITY, IL 60959</b>
---	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
--------------------	--	---------------	---	--------------------

S 000	Initial Comments	S 000		
	Annual Licensure and Certification Survey			
S9999	Final Observations	S9999		
	<p>Statement of Licensure Violations</p> <p>300.3130c)3)4)</p> <p>Section 300.3130 Plumbing Systems</p> <p>c) Water Supply Systems</p> <p>3) Hot water distribution systems shall be arranged to provide hot water of at least 100 degrees Fahrenheit at each hot water outlet at all times.</p> <p>4) Hot water available to residents at shower, bathing and handwashing facilities shall not exceed 110 degrees Fahrenheit.</p> <p>These requirements are not met as evidenced by:</p> <p>Based on observation, interview, and record review, the facility failed to maintain water temperatures between the required 100 degrees Fahrenheit and 110 degrees Fahrenheit. This failure has the potential to affect all 43 residents residing in the facility.</p> <p>Findings include:</p> <p>On 9/11/18 at 1:06 pm, the water from the hand sink of resident room 102 measured 122.5 degrees Fahrenheit (F). V3, Interim Maintenance Director, stated, "That's way too hot."</p> <p>The water from the hand sink in resident room</p>		<h2>Attachment A</h2> <h3>Statement of Licensure Violations</h3>	

Illinois Department of Public Health LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE	TITLE	(X6) DATE
---	-------	-----------

Illinois Department of Public Health

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  IL6003792	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____  B. WING: _____	(X3) DATE SURVEY COMPLETED  09/13/2018
--	---	--	--

NAME OF PROVIDER OR SUPPLIER  PIPER CITY REHAB & LIVING CENTER	STREET ADDRESS, CITY, STATE, ZIP CODE 600 MAPLE STREET PIPER CITY, IL 60959
--	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
S9999	<p>Continued From page 1</p> <p>109 measured 121.1 F.</p> <p>The water from the hand sink in resident room 107 measured 121.6 F.</p> <p>The water from the hand sink in resident room 117 measured 116.4 F.</p> <p>The water from the shower in the facility's 100 hall shower room measured 118.7 and was still rising when V3, Interim Maintenance Director, stated, "It doesn't matter, its already too hot."</p> <p>The water from the hand sink in resident room 203 measured 90.5 F, and the faucet handle loosely rotated in all directions and did not control the water temperature. V3, Interim Maintenance Director, stated "The handle is stripped."</p> <p>The water from the hand sink in room 215 measured 118.7 F.</p> <p>The water from the hand sink in room 214 measured 120.5 F.</p> <p>The water from the shower in the facility's 200 hall shower room, and from the hand sink in the 200 hall shower room, measured 120.5 F.</p> <p>The water from the hand sink in resident room 208 measured 120.2 F.</p> <p>On 9/12/18 at 3:48 pm, V4, V5, V6, and V7, Certified Nursing Assistants, stated that every resident in the facility goes in the shower, each resident in the facility has scheduled shower days either on day shift or evening shift.</p> <p>On 9/13/18 at 12:08 pm, V3, Interim Maintenance Director, stated, "The whole facility only has two</p>	S9999		

Illinois Department of Public Health

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  <b>IL6003792</b>	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____  B. WING: _____	(X3) DATE SURVEY COMPLETED  <b>09/13/2018</b>
--	--	--	---

NAME OF PROVIDER OR SUPPLIER  <b>PIPER CITY REHAB &amp; LIVING CENTER</b>	STREET ADDRESS, CITY, STATE, ZIP CODE <b>600 MAPLE STREET PIPER CITY, IL 60959</b>
---	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
S9999	<p>Continued From page 2</p> <p>water heaters, one goes to all of the resident rooms, and one goes to the kitchen and dishwasher."</p> <p>The facility's Resident Census and Conditions of Residents dated 9/11/18 documents 43 residents reside in the facility.</p> <p>(B)</p>	S9999		